

Transport SA

Rapid Bay Jetty

Structural Assessment Report

June 1998

Project No.: 10998.00

COPY NO. [2]


Maunsell Pty Ltd
Level 3
100 Pirie Street
Adelaide, 5000
South Australia

Tel: (08) 8232 0466
Fax: (08) 8232 0396

ACN 004 846 824

Rapid Bay Jetty

Structural Assessment Report

REVISION	REVISION DATE	DETAILS	AUTHORISED	
			NAME/POSITION	SIGNATURE
A	04/08/97	Draft to TSA for Comment	Tim Austin – Project Manager	Original Previously Signed
B	25/06/97	Issued to TSA	Tim Austin – Project Manager	

© Maunsell Proprietary Limited 1998

The information contained in this document produced by Maunsell is solely for the use of the Client identified on the cover sheet for the purpose for which it has been prepared and Maunsell undertakes no duty to or accepts any responsibility to any third party who may rely upon this document.

All rights reserved. No section or element of this document may be removed from this document, reproduced, electronically stored or transmitted in any form without the written permission of Maunsell Pty Ltd.

TABLE OF CONTENTS

1. INTRODUCTION	1
1.1 BACKGROUND AND OBJECTIVES	1
1.2 CONDUCT OF THE STUDY	1
2. STRUCTURAL CONDITION	3
2.1 JETTY DESCRIPTION	3
2.2 JETTY CONDITION	3
3. STRUCTURAL CAPACITY	5
3.1 DECKING	5
3.2 SUBSTRUCTURE	5
3.3 MACHINERY BAYS	6
3.4 PILING	7
4. STRUCTURAL CAPACITY INCREASE	8
4.1 CRITICAL STRINGERS	8
4.2 PILES	8
5. CONCLUSIONS	9
6. REFERENCES	10

1. INTRODUCTION

1.1 Background and Objectives

In July 1997 Transport SA commissioned Mausell Pty Ltd to assess the structural capacity of the Rapid Bay Jetty. This Report presents the results of that investigation.

The Rapid Bay Jetty was built in the early 1940s by the BHP Proprietary Company Ltd as a load out jetty for limestone from the adjacent quarry. Sections of it, especially the loading head, were rebuilt in 1968. BHP handed over the jetty to the Department of Marine and Harbors in 1981 after the company ceased shipping limestone from Rapid Bay and it became surplus to their needs.

Adelaide Brighton Cement (ABC) subsequently leased the jetty for load out of limestone for its Adelaide cement manufacturing operation. In the early-mid 1990's ABC stopped using Rapid Bay limestone and therefore the jetty. The conveyor system has subsequently fallen into disrepair.

The jetty is currently extensively used by recreational fishermen.

The piles and superstructure have suffered considerable corrosion and consequently the structural capacity of the jetty is much reduced from the original. Replacement of some deck sections has been carried out and supplementary steel piles and cross beams have been added since initial construction.

ABC now intends to dismantle and remove the conveyor system including pulleys, motors and gearboxes from the jetty.

ABC wishes to obtain a determination of the maximum axle load which can be sustained by the structure generally and in particular adjacent to the machinery shed locations. This will permit ABC to determine the optimum truck and crane types to use in the demolition work.

1.2 Conduct of the Study

1.2.1 Information

Copies of available drawings of the jetty together with a copy of DMH Report, Rapid Bay Jetty Structural Status, 1987 were provided by Transport SA.

1.2.2 Inspection

Maunsell personnel (T. Austin and D. Lee) inspected the jetty on 11 July 1997. This comprised a visual inspection from the deck only. The underside was not inspected from below and specific member thickness measurements were not taken.

General corrosion condition of the members was noted together with any critical areas. A series of photographs were taken and copies are included in Appendix B to this Report.

1.2.3 Analysis

The various jetty element were analysed using a conservative worst case estimate of the member thicknesses and allowing a 15% Factor of Safety applied to working stress calculations.

For most elements a single point load was applied at centre span, representing the rear wheel of a vehicle. Spans are such that, with this scenarios, the front wheel of a typical design vehicle would be supported by the adjacent span.

The exception was the 0.35 m span stringers. In this case, a 3.5 m wheelbase vehicle was adopted with a 0.6:1.0 front:rear load ratio.

No load sharing was assumed between adjacent similar elements, ie the member under consideration was subjected to the full wheel load at its centre point. The same approach was taken with the piles; the wheel load was directly applied to the top of the pile, without inclusion of the intermediate supporting members.

Results of the analysis appear in Sections 3 and 5. The calculations are included in Appendix A.

Supplementary calculations to determine the scale of any repairs to critical areas are also included in Appendix A. The results of these are summarised in Section 4.

2. STRUCTURAL CONDITION

2.1 Jetty Description

The jetty can be divided into two sections, namely, the approach jetty (Bent 1 to Bent 80 approximately 467 m long) and the 'T' head (Bent 81 onwards, approximately 200 m long).

The older approach jetty section generally comprises of 225 x 75 mm timber decking and 225 x 150 mm timber cross beams supported on steel 330 x 125 mm TFB stringers and double 300 x 88 mm steel channel cross heads. Piles are 450 diameter timber. Additional steel piles at some bents have been used to supplement the original corroded timber piles for strength and stability. The 'T' head section has a similar arrangement except that the structure is solely supported by deep I-section steel crossheads and steel piles.

A typical cross section is as shown in Figure 2.1.


The two motor rooms are located between Bents 37 and 38 and Bents 79 and 80.

2.2 Jetty Condition


There is a high variation in condition for different parts of the jetty, although the general condition can be considered as poor. Serious degradation of steelwork is reflected by the fact that most of the pile bracing has rusted away. Moreover, a large portion of stringers and crossheads are in a state of moderate to severe corrosion.

It is common that the flange thicknesses of stringers and crossheads appear to be reduced to less than half of their original dimensions. At Bent 17, in particular, the seriously corroded crossheads are twisted with the western stringer detached although the neighbouring structure is still in serviceable condition.

Previous replacement of timber decking is observed at the approach jetty on the eastern side of the original location of the removed conveyor. The approach jetty is supported by a mixture of timber piles and steel piles. The degree of corrosion for timber piles ranges from zero diameter to their original diameter just above seal level. The steel piles exhibit significant corrosion to the flange edges in the inter-tidal zone but are considered serviceable and adequate. Critical bents exist where there are no replacement steel piles for those fractured timber piles (eg Bents 27 and 32).



Cross Section



View A

Figure 2.1 Typical Jetty Construction

3. STRUCTURAL CAPACITY

3.1 Decking

The jetty deck comprises of 5" x 7" (DMH 225 x 150 mm) ironbark cross beams supporting 10" x 3" (DMH 225 x 75 mm) tallow wood deck planks. A constant decking arrangement is found throughout the whole jetty where the centre-to-centre distance of the cross beams is 800 mm. In the approach jetty section, timber planks run along the length of the jetty. The eastern 3 m width section, which has been replaced previously, is in a better condition than the rest.

From the structural analysis of these two decking components, it is the deck plank which presents the more critical load limitation. In fact, it is one of the most critical components of the whole jetty structural system. The deck planks are assumed to function separately, ie there is no load sharing between plans.

A maximum wheel load of 2.7 tonne was determined by applying a single wheel load at the mid span of a single typical deck plank. A Factor of Safety of 1.15 was adopted, which accounts for the variation in the timber condition.

The timber cross beam capacity is 3.0 tonne, assuming a single wheel directly over the cross beam and no counterbalancing between spans.

If a dual wheel truck distributes the wheel load to two planks, the maximum allowable wheel load would increase to 5.4 tonnes.

Similarly, the load imposed on any plank by crane outrigger loads at the motor room bays must be kept within the 2.7 tonne limit by the use of a spreader plate across two or more deck planks.

A 500 x 500 x 20 mm thick steel plate would adequately distribute the point load to two planks. Alternatively appropriate timber spreaders may be used.

3.2 Substructure

Both the 13" x 5" (330 x 125 mm) TFB stringers and 12" x 3.5" (300 x 88 mm) channel cross heads were structurally analysed to assess their residual strengths in their present condition.

(a) Crosshead

For the crosshead, the flange thickness was assumed to be reduced to 5 mm from the original thickness of 13.6 mm, while the web thickness was 8 mm instead of the original 10.16 mm. In this generalised case, the adopted dimensions were taken at the worst section of the crossheads. A conservative simply supported span between two piles with a point load at mid-span was considered (ie the wheel is directly over the crosshead). A maximum allowable wheel load of 7 tonne resulted. It is clear that even with such severe corrosion, the crosshead is not the critical part of the whole structural system.

(b) Stringer - 4.5 m span

A more elaborate approach to the calculation of the stringer's residual strength was carried out which has considered the corrosion and the drilled holes at their flanges. The wheel load was assumed to be directly over a stringer (ie no load sharing) and any counterbalancing from other wheel loads in the adjacent span was ignored. A 33% remaining flange thickness and 83% remaining web thickness were adopted (ie 5 mm and 10 mm respectively). A two-span model having a mid-span point load in only one span gave the highest resultant moment. A 4.5 tonne maximum allowable wheel load resulted.

(c) Stringer - 9.35 m span

In several locations, eg Bents 27 and 32, the pile bent provides no support to the stringers because of pile failure. The stringers are therefore spanning across two bays, ie 9.35 m.

For this situation, a 3.5 m wheel base vehicle was assumed, with a front wheel load of 0.6 x the rear wheel load. This results in a maximum rear wheel load of 1.0 tonne compared with 4.5 tonne for the 4.5 m span. The corresponding front wheel load is 0.6 tonne.

There are several approaches which could be adopted to improve these critical spans. These are discussed in Section 4 below.

3.3 Machinery Bays

The machinery bays refer to bays between Bents 37 to 38 and Bents 79 to 80 under lifting conditions where motor rooms are situated, and they are prospective locations for a stationary crane. Additional steel UB cross heads and steel piles are located adjacent to the typical timber pile bents. By inspection, these additional supporting steel structures, which are in a reasonable condition, would not form any limitation to the size of the crane nor become a critical component of the structural analysis for these sections of the jetty.

The maximum wheel or outrigger load will be governed by the capacity of the stringers, assuming that appropriate steps are taken to spread the loads across the deck planks, as discussed above.

This limiting load will be as discussed under 3.2(b) above. This could be increased by ensuring that the point of application of the load is coincident with the UB crossheads. This would necessitate the use of temporary support beams under the outriggers and spanning between the crossheads.

However, it is considered that the limiting condition will not be the stationary crane operating at the machinery bay but rather the unladen wheel loads imposed by the same crane travelling down the approach jetty.

3.4 Piling

For Bents 1 to 7, the timber piles are generally in good condition. Bent 8 to Bent 26, the timber piles are subjected to varying degrees of corrosion/degradation and are non-functional. They have been replaced with steel piles. Additional steel piles and crossheads are located at every fifth bent from Bent 28 to the jetty head while the 'T' head and motor rooms are supported by steel piles. Generally, the steel piles are in a reasonable state and critical locations exist at the timber pile bents.

Thus, a critical location exists between Bents 29 to 31 where the remaining timber pile diameter at Bent 30 is about 200 mm, compared with the original 450 mm. Even with only 20% remaining of the original cross-sectional area, an estimated 2.2 tonnes allowable wheel load was obtained based on an assumed typical truck wheel load configuration.

Complete loss of pile capacity is covered under 3.2(c) Stringer - 9.35 m, above.

4. STRUCTURAL CAPACITY INCREASE

4.1 Critical Stringers

The critical spans at the missing Bents 27 and 32 present a significant limitation to vehicle size traversing the jetty. There are several approaches available to deal with this restriction:

1. **Accept as is** - this limits the load to a 2 tonne axle load.
2. Replace the 9.35 long stringers with two new 310 UB 46.2 beams in the line of the wheels. This would increase the stringer allowable wheel load to 3.1 tonne.
3. Repair the broken piles which would restore the 4.5 m span and raise the stringer limit to 4.5 t (see 3.2(b) above). Vertical steel straps bolted to the sound pile sections could be used.

Choice of approach will depend on the relative costs and merits of the alternatives. Alternative 1 is clearly cheaper but would restrict the demolition operation significantly. Alternative 3 would most likely be less expensive than Alternative 2 assuming a straight forward bolted connection arrangement could be devised. It also provides a higher allowable load.

4.2 Piles

The 2.2 tonne limit imposed by degraded piles at some locations could be increased to 6.5 tonne by an increase of equivalent cross sectional diameter to 250 mm. This could be achieved by repair of the piles as described in Alternative 3 in 4.1 above.

5. CONCLUSIONS

The structural capacity of the jetty is limited by the capacity of the existing elements; deck, bearers, steel stringers, steel crossheads and timber piles. The maximum wheel loads available are as summarised in Table 5.1.

Table 5.1 Allowable Wheel Loads

Element	Wheel Load Tonne	Comment
Single deck plank 225 x 75 tallow wood	2.7	Load per plank. Dual wheels would increase this to 5.4 tonne
Cross beam 225 x 150 ironbark	3.0	
Stringer, 4.47 m span, 330 x 125 TFB	4.5	Corroded, drilled hole, two spans
Stringer, 9.35 m span, 330 x 125 TFB	1.0	3.5 m wheelspan, front wheel load 0.6 t
Crosshead, 2 x 300 x 88 channels	7.0	Corroded, one span
Piles 450 diameter timber	140	Based on full diameter, full length (ie new pile)
Piles 200 diameter timber	2.2	Conservatively based on 200 diameter for full length
Piles 250 diameter	6.5	Based on 250 diameter for full length

In summary, for Bents 1 to 26, assuming a dual wheeled vehicle, the cross beam would govern, resulting in a maximum 3 tonne wheel load or 6 tonne axle load.

At two specific locations (Bents 27 and 32) where pile bents are ineffective, the stringer governs, resulting in a maximum 1 tonne wheel load or 2 tonne axle load. This limitation could be removed by repair of the piles.

For Bents 28 - 80, the piles govern generally (except for the steel piles at every fifth bent which are not limiting), resulting in a maximum wheel load of 2.2 tonne or axle load of 4.4 tonne. This could be increased by repair of the piles.

In the machinery bays, the deck and cross beams govern as for the approach jetty. This limitation could be increased or removed by the use of outrigger spreader plates or beams between crossheads.

6. REFERENCES

Department of Marine and Harbors, Rapid Bay Jetty Structural Status 1987, Adelaide 1987

Drawings, Rapid Bay Jetty, various by BHP Co. Ltd 1940, 1941, 1965 and 1968 and DMH 1979.

What about
reference to
1992 DMH Report
Why was this not
referred to ???

Maunsell

RAPID BAY JETTY

JOB No. 10998

BY RL.

SHEET No. A 1

SUMMARY OF JETTY CONDITIONS

CHECKED

DATE July '97.

SUBSTRUCTURE

SURSTRATE

- 79-80 → STEEL PILES
(No 3 motor Rm)
- ALL STEEL PILES

- Old decking

- 28 & EVERY 5TH BENTS
→ STEEL RAKER PILES

- 30 → v. poor stringer condition

- 37-38 → STEEL PILES
(No. 2 motor Rm)

- 70 → TIMBER PILES +
STEEL SIDE PILES

- 76, 78 → ADDITIONAL STEEL PILE
ON EASTERN SIDE

(NB Very poor condition
at Bents 27 & 32)


- 10 → 26 → STEEL PILES
(raking + vertical)

- 17 → v poor Cross Head Condition

- 13, 18, 23 → DOUBLE RAKER PILES

- 1-7 → TIMBER PILES
- 8-10 → STEEL PILES
(raking + vertical)

- 8 → v. poor Stringer Condition



BENTS
26-78

BENTS
10-26

BENTS
1-10

APPENDIX A

CALCULATIONS

RAPID BAY JETTY	Maunsel	
APPENDIX A - CALCULATION		
	BY PL,	SHEET No.
CHECKED	DATE July '97	

CONTENT :

- SUMMARY OF JETTY CONDITION	A 1
- GIRDER CHECK	A 5
- GIRDER : CRITICAL CASE	A 13
- CROSS HEAD CHECK	A 17
- PLANK CHECK	A 18
- CROSS BEAM CHECK	A 20
- SUMMARY OF PERMISSIBLE WHEEL LOAD	A 21
- STEEL PAD DESIGN	A 22
- TIMBER PILE CHECK	A 24

Maunsell

RAPID BAY JETTY

JOB No. 10998

BY DL.

SHEET No. A 1

CHECKED

DATE July '97.

SUMMARY OF JETTY CONDITIONS

SUBSTRUCTURE

SUBSTRATE

• 79-80 → STEEL PILES
(No. 3 MOTOR RM)

• Old decking

• ALL STEEL PILES

• 28 & EVERY 5TH BENTS
→ STEEL RAKER PILES

• 30 → v. poor stringer condition

• 37 → 38 → STEEL PILES
(No. 2 MOTOR RM)

• 70 → TIMBER PILES +
STEEL SIDE PILES

• 76, 78 → ADDITIONAL STEEL PILE
ON EASTERN SIDE

(NB Very poor condition
at Bents 27 & 32)


• 10 → 26 → STEEL PILES
(raking + vertical)

• 17 → v. poor Cross Head Conditi

• 13, 18, 23 → DOUBLE RAKER PILES

• 1-7 → TIMBER PILES
• 8-10 → STEEL PILES
(raking + vertical)

• 8 → v. poor Stringer Conditi



Maunsel

RAPID BAY JETTY

JOB No. 10998


BY DL.

SHEET No. A 2

CHECKED

DATE July '97.

SUMMARY OF JETTY CONDITION FROM
BENT 1 TO BENT 80



RAPID BAY JETTY		Maunsell	
VISUAL INSPECTION		JOB No. 10998	
		BY D.L.	SHEET No. A 3
		CHECKED	DATE July 97

(A) SUBSTRUCTURE

<u>BENT</u>	<u>PILE</u>	<u>CONDITION</u>
1-7	TIMBER	
8-26	STEEL (Raking + Vertical)	GOOD
	TIMBER	OK
27	TIMBER	
28	STEEL (2x Raking - inside)	27 - V. poor
29-32	TIMBER	
33	STEEL	#290 - 29-31
	TIMBER	V. poor - 32
34-36	TIMBER	
37-38	STEEL (NO. 2 MOTOR RM)	
39-47	TIMBER	
48	STEEL	
49-58	TIMBER	
58	STEEL	
59-67	TIMBER	
68	STEEL	
69	TIMBER	
70	STEEL (OUTER) / TIMBER	
71-75	TIMBER	
76	STEEL (ON EASTERN SIDE)	
	TIMBER	
77	TIMBER	
78	STEEL (ON EASTERN SIDE)	
	TIMBER	
79-80	STEEL (NO. 3 MOTOR RM)	
81 & ONWARDS	STEEL	

RAPID BAY JETTY		Maunsel	
		JOB No. 10998	
VISUAL INSPECTION		BY DL	SHEET No. A 4
		CHECKED	DATE July '98

(B) SUBSTRATE STEELWORK

BENT	GIRDER/STRINGER	CROSSHEAD	REMARKS
1-7			
8	5	2	
9	1	3	
10	1	2	
11	3	1	
12	3	4	
13-16	3	4	
17	3	5	
18	3	4	cross head twisted
19-26	4	4	
27-29	4	4	girders span from 26-28
30	5	4	
31-36	4	4	
37-38			girders span from 31-33
39-47	4	4	+
48		1	
49-57	4	4	+
58		2	
59-67	4	4	+
68		2	
69-78	+	4	+
79-80		2	
81 & ONWARDS	2	2	✓

NS:

• CODE : 1 — 5
GOOD — POOR

• * ~ ADDITIONAL I SECTION CROSSHEAD & STEEL PILING SYSTEM

RAPID BAY JETTY

JOB No. 10998

GIRDER CHECK

BY D.L.

SHEET No. A 6

CHECKED

DATE July '97

(I) NO CORROSION :

$$13" \times 5" \text{ TFR} \Rightarrow Z = 43.63 \text{ in}^3$$

$$Z_{xx} = 714.8 \times 10^3 \text{ mm}^3$$


$$f_b = 165 \text{ MPa}$$

$$f_b = \frac{M_{all}}{Z_{xx}}$$

$$M_{all} = 165 \times 714.8 \times 10^3 \text{ mm}^3$$

$$\therefore M_{all} = 118 \times 10^6 = 118 \text{ kN-m}$$

WORST CASE :



FROM SPACE GAGE


$$P_{max} \approx 120 \text{ kN}$$

ie. 12.2 tonnes / wheel

$$(M_{max} = 111.6 \text{ kN-m})$$


RAPID BAY JCT	Maunsel	
GIRDER CHECK	JOB No. 10998	
	BY J.L.	SHEET No. A 7
	CHECKED	DATE July '97

(A) TYPICAL CASE



Assuming a 4t truck load { Single wheel
2 axles

CRITICAL CASE - WHERE LOAD (REAR WHEEL LOAD) AT MID-SPAN



LOADING :

(i) DL :

$$\text{DECK PLANK} = 1000 \text{ kg/m}^3 \times 0.076 \times \frac{9.81}{1000} = 0.75 \text{ kN/m}$$

$$\text{CROSS BEAM} = 1100 \text{ kg/m}^3 \times 0.178 \times 0.127 \times \frac{6}{4.47} \times \frac{9.81}{1000} = 0.33$$

$$\text{GIRDER SW} \approx 50 \text{ kg/m} \times \frac{9.81}{1000} = 0.5 \text{ kN/m}$$



$$\Rightarrow \Sigma DL = (0.75 + 0.33) 1.38 + 0.5 \text{ kN/m}$$

$$= 1.99 \text{ kN/m}$$

$$\approx 2.1 \text{ kN/m} \text{ including hand rail etc}$$

(ii) L.L. : WHEEL LOAD

A7



ORDER (1) No CORROSION

5: Unnamed, Designer: DL, Units: m,kN,kNm, Scale: 1:66, Axes: XY
 ad: 42 Disp: None Moment: None Shear: None Axial: None
 SPIDBAY JETTY
 998
 16 Jul 1997 11:47

16 Jul 1997, 11:47 am

MEMBER FORCES AND MOMENTS (kN,kNm)

Load case 3 (Linear): DL+LL

Memb	Node	Axial Force	Y-Axis Shear	Z-Axis Shear	X-Axis Torsion	Y-Axis Moment	Z-Axis Moment
1	1	0.000	52.270	0.000	0.000	0.000	0.000
	2	0.000	47.577	0.000	0.000	0.000	111.579
2	2	0.000	-72.423	0.000	0.000	0.000	(111.579)
	3	0.000	-77.117	0.000	0.000	0.000	-55.532
3	3	0.000	17.117	0.000	0.000	0.000	-55.532
	4	0.000	12.423	0.000	0.000	0.000	-22.521
4	4	0.000	12.423	0.000	0.000	0.000	-22.521
	5	0.000	7.730	0.000	0.000	0.000	0.000

NODE REACTIONS (kN,kNm)


Load case 3 (Linear): DL+LL

Node	X-Axis Force	Y-Axis Force	Z-Axis Force	X-Axis Moment	Y-Axis Moment	Z-Axis Moment
1	0.000	52.270	0.000	0.000	0.000	0.000
3	0.000	94.234	0.000	0.000	0.000	0.000
5	0.000	-7.730	0.000	0.000	0.000	0.000
Load	0.000	-138.774	0.000			
Reac	0.000	138.774	0.000			

RAPID RAY JETTY	Maunsel	
	JOB No. 10998	
GIRDER CHECK	BY D.L.	SHEET No. 49
	CHECKED	DATE July '9

(II) CORRODED GIRDER :

Generally corrosion varies at different locations, conservatively, take 5 mm for flange thickness and 10 mm for web thickness.



$$I_{xx} = \frac{127 \times 330^3}{12} - \frac{117 \times 320^3}{12}$$

$$= 60.845 \times 10^6 \text{ mm}^4$$

$$Z_{xx} = \frac{I_{xx}}{y} = \frac{60.845 \times 10^6}{165}$$

$$= 368.76 \times 10^3 \text{ mm}^3$$

$$\therefore Z_{xx} (\text{COR}) = 368.8 \times 10^3 \text{ mm}^3$$

$$\approx 52\% \text{ OF } Z_{xx} (\text{NEW})$$

$$\Rightarrow M_{all} = 165 \times 368.8 \times 10^3$$

$$= 60.85 \text{ kN-m}$$



FROM SPACE GASS

$$P_{max} = 60 \text{ kN}$$

ie 6.1 tonnes / wheel

$$(M_{max} = 57.1 \text{ kN-m})$$

1	-----	DL
2	-----	LL
3	-----	DL+LL



GIRDER-CORRODED

Job: RAPBAY, Designer: DL, Units: m,kN,kNm, Scale: 1:66, Axes: XY
 Load: .42 Disp: None Moment: None Shear: None Axial: None
 RAPIDBAY JETTY
 0998

16 Jul 1997, 2:11 pm

MEMBER FORCES AND MOMENTS (kN,kNm)

Load case 3 (Linear): DL+LL

Membr	Node	Axial Force	Y-Axis Shear	Z-Axis Shear	X-Axis Torsion	Y-Axis Moment	Z-Axis Moment
1	1	0.000	27.895	0.000	0.000	0.000	0.000
	2	0.000	23.202	0.000	0.000	0.000	57.101
2	2	0.000	-36.798	0.000	0.000	0.000	(57.101) ←
	3	0.000	-41.492	0.000	0.000	0.000	-30.389
3	3	0.000	11.492	0.000	0.000	0.000	-30.389
	4	0.000	6.798	0.000	0.000	0.000	-9.949
4	4	0.000	6.798	0.000	0.000	0.000	-9.949
	5	0.000	2.105	0.000	0.000	0.000	0.000

NODE REACTIONS (kN,kNm)

Load case 3 (Linear): DL+LL

Node	X-Axis Force	Y-Axis Force	Z-Axis Force	X-Axis Moment	Y-Axis Moment	Z-Axis Moment
1	0.000	27.895	0.000	0.000	0.000	0.000
3	0.000	52.984	0.000	0.000	0.000	0.000
5	0.000	-2.105	0.000	0.000	0.000	0.000
Load	0.000	-78.774	0.000			
Reac	0.000	78.774	0.000			

RADID BAY JETTY	Maunsel	
	JOB No. 10998	
GIRDER CHECK	BY DL	SHEET No. 12
	CHECKED	DATE July 97

DUE TO THE DRILLED HOLES ($\phi = 20 \text{ mm}$) @ 914 mm CTS, THE MOMENT CAPACITY SHOULD BE REDUCED ACCORDING

$$Z_{xx} (\text{new}) = 714.8 \times 10^3 \text{ mm}^3$$

$$Z_{xx} (\text{hole}) = 635.16 \times 10^3 \text{ mm}^3 \quad (\text{from BHP tables 1961})$$

$$= 89\% \times Z_{xx} (\text{new})$$

FOR CORRODED GIRDER:

$$Z_{xx} (\text{cor, hole}) = 0.89 \times 368.8 \times 10^3$$

$$= 327.7 \times 10^3 \text{ mm}^3$$

$$P_{\text{max}} \approx 53.4 \text{ kN} \quad (= 0.89 \times 60 \text{ kN})$$

ie 5.2 tonnes / wheel

IN VIEW OF THE EXTENSIVE CORROSION AND LIMITATIONS ON THIS VISUAL INSPECTION, A SAFETY FACTOR OF 1.15 IS APPLIED.


$$\therefore \text{MAX. WHEEL LOAD} = \frac{5.2}{1.15}$$

$$= 4.5 \text{ tonnes / wheel}$$

RAPID EAY JETT	Maunsell	
	JOB No.	10998
GIRDER CHECK	BY DL	SHEET No. A 13
	CHECKED	DATE July 97

(B) CRITICAL CASE :

CRITICAL LOCATIONS OCCUR AT BENTS 27 & 32 WHERE THE
TIMBER PILES ARE AT VERY POOR CONDITIONS AND
THE GIRDERS ARE ASSUMED TO SPAN TWO SPANS.



$$Z_{xx} (\text{hole, corr}) = 327.7 \times 10^3 \text{ mm}^3$$

$$M_{all} = 165 \times 327.7 \times 10^3 \times \frac{1}{1.15} = 47 \text{ kN-m}$$

$$R_2 = \frac{12.3 \times 2.72 + 22.1 (8.94 - 2.72)}{8.94} = 19.12 \text{ kN}$$

$$M_{max} = R_2 \times 2.72 = 52 \text{ kN-m}$$

$$w_L = 2.1 \text{ kN/m}$$

$$M_{max, DL} = \frac{wL^2}{8} = \frac{2.1 \times 8.94^2}{8} = 21 \text{ kN-m}$$


$$\therefore \text{TOTAL MOMENT} = 52 + 21 = 73 \text{ kN-m} > M_{all}$$

$$M_{max} \text{ due to wheel load} = 47 - 21 = 26 \text{ kN-m}$$

$$M_{max} \text{ mid-point load} = \frac{4 \times M}{l} = 11.6 \text{ kN} \approx 1.18 \text{ tonnes/wheel}$$

RAPID ERM JETTY	Maunsell	
GIRDER CHECK	JOB No. 10998	
	BY DL.	SHEET No. 14
	CHECKED	DATE July 97

(i) ALTERNATIVE 1 : (LIMITING MAX. WHEEL LOAD)



$$Z_{rx} \text{ (hole, corr.)} = 327.7 \times 10^3 \text{ mm}^3$$

$$M_{allow} = 165 \times 327.7 \times 10^3 \times \frac{1}{1.15} = 47 \text{ kN-m}$$

$$R_{2,P} = \frac{P \times 2.925 + 1.8P \times (9.35 - 2.925)}{9.35} = 1.55P$$

$$M_{max,P} = R_{2,P} \times 2.925 = 4.533P$$

$$DL_{TIMBER} = 2.1 \text{ kN/m}$$

$$M_{DL} = \frac{2.1 \times 6.425}{2} (9.35 - 6.425) = 19.73 \text{ kN-m (at } x = 6.425 \text{ m)}$$

$$\therefore \text{TOTAL MOMENT} = M_{max} = M_{max,P} + M_{DL}$$

$$= 4.533P + 19.73$$

$$\Rightarrow M_{allow} > M_{max}$$

$$\Rightarrow 47 \text{ kN-m} > 4.533P_{max} + 19.73$$

$$P_{max} < 6.0 \text{ kN}$$

$$\therefore \text{Max wheel load} = 6.0 \text{ kN/wheel}$$

$$\text{Moment at mid-span} \quad R_1 = \frac{P(6.425) + 1.8(2.925)P}{9.35} = 1.25P$$


$$M_{mid} = 1.25P \times \frac{9.35}{2} - P\left(\frac{9.35}{2} - 2.925\right) + \frac{2.1 \times 9.35^2}{8} \leq 47$$

$$\Rightarrow P_{max} = 5.875 \text{ kN/wheel}$$

$$\text{Max wheel load} = 0.6 \text{ tonnes/wheel} \leq 1.08 \text{ tonnes/wheel}$$

RAPID BAY JETTY	Maunsell	
GIRDER CHECK	JOB No. 10998	
	BY D.L.	SHEET No. A 15
	CHECKED	DATE July '97

(1) ALTERNATIVE 2 : (REPLACING GIRDER)



$$P = 1.39 \text{ t}$$

$$= 13.64 \text{ kN}$$

$$M_{\text{mid}} = 1.25P \times \frac{9.35}{2} - P \left(\frac{9.35}{2} - 2.925 \right) + \frac{2.1 \times 9.35^2}{8}$$

$$= 78.8 \text{ kN-m}$$

$$f_b = \frac{M}{Z}$$

$$Z_{\text{required}} = \frac{M}{f_b} = \frac{78.8 \times 10^6}{\frac{165}{1.15}} = 549.12 \times 10^3 \text{ mm}^3$$

USE 310 UB 46.2
(OR 360 UB 44.7)

$$Z_x = 654 \times 10^3 \text{ mm}^3$$

$$Z_x = 669 \times 10^3 \text{ mm}^3$$

FOR 310 UB 46.2

$$\phi M = f_b \times Z = \frac{165}{1.15} \times 654 \times 10^3 \text{ mm}^3$$

$$= 93.83 \text{ kN-m}$$

$$M_{\text{max}} = 1.25P \times \frac{9.35}{2} - P \left(\frac{9.35}{2} - 2.925 \right) + \frac{2.1 \times 9.35^2}{8} = 93.83$$

$$4.09375 P + 22.95 = 93.83$$

$$\Rightarrow P = 17.3 \text{ kN}$$

$$\Rightarrow \text{max wheel load} = 1.8P = 31.2 \text{ kN}$$

Maunsel

RAPID BAY JETTY

JOB No. 10998

GIRDER CHECK

BY 2L,

SHEET No. 16


CHECKED

DATE July '97

(iii) ALTERNATIVE 3 : (FIXING THE BROKEN PILES).

Assuming Max. load = $P = 3 \text{ tonnes} \div 29.4 \text{ kN}$

$$P/4 = 7.4 \text{ kN}$$




Moment caused by timber pile buckling is small.

$$P^* \div 2 \times 7.4 \div 14.8 \text{ kN}$$

USE 75/75 x 8 EA $\phi N = 79.5 \text{ kN}$

$$V^* \text{ on 1 bolt} = 29.4 \times 2/8 = 7.35 \text{ kN}$$

$$\underline{m16} \Rightarrow \phi V_{fn} = 28.6 \text{ kN}$$



Maunsell

RAPID BAY JETTY

JOB No. 10998

DECK PLANK CHECK


BY D.L.

SHEET No. 18

CHECKED

DATE July '97

PLANK : $254\text{mm} \times 76\text{mm}$
 $10" \times 3"$ Decking - Tallow Wood
Stress grade = F17



BENDING :

$$F_b = 17 \text{ MPa}$$

$$k_1 = 1.7 \quad k_2 = 1 \quad k_3 = 1.05 \quad k_4 = 0.15 \quad k_5 = 1 \quad k_6 = 1 \quad k_7 = 1$$
$$k_{12} = 1$$

$$\therefore F_b = 1.7 \times 1.05 \times 0.15 \times 17 = 19.7 \text{ MPa}$$

Assume double span :

$$M = 0.178 PL$$

$$f = \frac{0.178 PL}{Z} \Rightarrow P = \frac{fZ}{0.178 \times L}$$

$$= \frac{19.7 \times 250 \times 75^2}{0.178 \times 800 \times 6} = 32.424 \text{ kN}$$

≈ 3.3 tonnes / wheel.

RAPID BAY JETTY	Maunsel	
DECK PLANK CHECK	JOB No. 10998	SHEET No. A 19
	BY DL	DATE July '97

SHEAR:

$$F's = 1.47 \text{ MPa}$$

$$F_s = k_1 k_2 k_3 k_4 k_5 k_6 F's$$

$$= 1.7 \times 1 \times 1.05 \times 0.65 \times 1 \times 1.47 = 1.68 \text{ MPa}$$

$$\sigma = \frac{F}{A} = \frac{V}{A}$$


$$\Rightarrow V = F_s \times A = 1.68 \times 250 \times 75 = 31.5 \text{ kN}$$

$$\approx 3.2 \text{ tonnes/wheel.}$$

TO TAKE INTO ACCOUNT OF THE CONDITION OF TIMBER PLANK (ESPECIALLY TRUE FOR AREA NEAR JETTY HEAD), A FACTOR OF SAFETY OF 1.15 IS APPLIED

$$\therefore \text{MAX. WHEEL LOAD} = 3.2 \times \frac{1}{1.15}$$

$$= 2.78 \text{ tonnes/wheel}$$



RAPID EAY JETTY	Maunsel	
CROSS BEAM CHECK	JOB No. 10996	
	BY D.L.	SHEET No. 20
	CHECKED	DATE July 97.


CROSS BEAM :

178mm 127mm

7" x 5"

Ironbark

Stress grade : F17



BENDING :

$$F_b = C_1 C_2 C_3 C_4 C_5 C_6 C_7 C_8 F_b'$$

$$= 1.7 \times 1 \times 1 \times 0.62 \times 1 \times 1 \times 1 \times 1 \times 17 = 17.92 \text{ MPa}$$

$$\text{Due to Deck + SHY } W_{DL} = 0.75 \text{ kPa} \times 0.914 + 0.25$$

$$= 0.94 \text{ kN/m}$$

$$M_{max} = 0.07 \times 0.94 \times 1330^2 + 0.15 P \times 1330$$

$$P = \left(17.92 \times \frac{175^2 \times 125}{6} - 116393.62 \right) \frac{1}{0.15 \times 1330}$$

$$= 51.73 \text{ kN}$$

$$\approx 5.8 \text{ tonnes/wheel}$$

SHEAR :

$$F_s = 1.7 \times 1 \times 1 \times 0.62 \times 1.45 = 1.53 \text{ MPa}$$

$$V_{max} = 1.53 \times 178 \times 127 = 34.5 \text{ kN}$$

$$\approx 3.5 \text{ tonnes/wheel}$$

$$\text{max wheel load} = 3.5 \times \frac{1}{1.15} = 3 \text{ tonnes/wheel}$$

⇒ LESS CRITICAL THAN DECK PLANK

RAPID BAY JETTY	Maunsel	
	JOB No. 10998	
	BY TL	SHEET No. A 21
	CHECKED	DATE July 97

SUMMARY OF PERMISSIBLE WHEEL LOAD FOR SUBSTRATE

<u>STRUCTURAL MEMBER</u>		<u>PERMISSIBLE WHEEL LOAD</u> <u>(tonnes/wheel)</u>
1.	GIRDER (TFB)	4.5
2.	CROSSHEAD (DOUBLE CHANNEL)	7
3.	DECK (TIMBER PLANK)	2.78
4.	CROSS BEAM (TIMBER)	3

* CRITICAL LOCATION AT BENT 26 - 28 & BENT 31 - 33 .

RAPID BAY JETTY

Maunsell

JOB No. 10998

DECK PLANK CHECK - STEEL PAD DESIGN


BY D.L.

SHEET No. A 22

CHECKED


DATE July '97

IN ORDER TO REDUCE CRANE SUPPORT PRESSURE, STEEL PADS ARE PLACED UNDERNEATH THE SUPPORTS FOR SPREADING LOADS TO LARGER DECK AREAS.



ASSUME THE PAD AREA IS $500 \times 500 \text{ mm}^2$

FOR 1 PLANK:



$$M_{max} = 0.096 \times \frac{P}{2} \times 0.8 \times 0.8 = 0.0307 P \quad (\text{KN-m or } 10^6 \text{ N-mm})$$

$$F_b = 19.7 \text{ MPa}$$

$$F.O.S = 1.15$$

$$\Rightarrow F_b = 17.13 \text{ MPa}$$

$$\sigma = \frac{M}{Z}$$

 \Rightarrow

$$17.13 = \frac{0.0307 \times P \times 6 \times 10^6}{250 \times 75^2}$$

$$\Rightarrow P = 130.7 \text{ kN}$$

$$\approx 13.3 \text{ tonnes}$$

RAPID BAY JETTY

Maunsell

JOB No. 10998


DECK PLANK - STEEL PAD DESIGN

BY D.L.

SHEET No. A 23

CHECKED

DATE July '97



$$w = \frac{130.7}{0.5 \times 0.5} = 522.8 \text{ kPa}$$

$$w^* \approx 784.2 \text{ kPa}$$

$$m^* = 522.8 \times 0.5 \times 0.2 \times \frac{0.2}{2} = 5.3 \text{ kN-m}$$

$$\sigma = \frac{m}{Z}$$

$$280 \text{ mPa} = \frac{5.3 \times 10^6 \text{ N-mm}}{Z}$$

$$Z = 18929 \text{ mm}^3 = \frac{BD^2}{6}$$

$$\Rightarrow D_{\min} = \sqrt{\frac{18929 \times 6}{500}}$$


$$= 15 \text{ mm}$$

\therefore CHOOSE $D = 20 \text{ mm}$

\therefore PAD = $500 \times 500 \times 20 \text{ mm}$

P allow depends on the point of application.
(PLANK IS NOT CRITICAL)

RAPID BAY JETTY	Maunsell	
TIMBER PILE CHECK	JOB No. 10998	
	BY DL	SHEET No. A. 24
	CHECKED	DATE July 97



FOR BENTS 1-7, the timber piles are generally in good conditions. From BENT 8 onwards, timber piles are subjected to different degrees of corrosion/degeneration with steel piles replacing timber piles from Bent 8-26 which are non-functional due to their poor conditions. Additional steel piles are located at every fifth bent from bent 28 to Jetty head where the platform and Motor Room is supported by steel I section piles.

Critical locations shall be at the timber piles without steel pile supporting.

RAPID BAY JETTY	Maunsel	
TIMBER PILE CHECK	JOB No. 10998	BY D.L.
	CHECKED	SHEET No. A 25 DATE July '57.

AT Bents 29-31, the remaining timber pile diameter is about 200 mm just above sea level.

Original diameter = 450 mm.

$$\% \text{ of area remaining} = \frac{100^2}{225^2} \times 100\% = 20\%$$

$$DL: \overset{\text{DECK}}{(0.75 \text{ kPa} + \overset{\text{CROSS BEAM}}{0.33 \text{ kPa} + \overset{\text{GIRDER}}{0.5 \times 4 / 6.47}) \times 4.88 \times 2.44} + \overset{\text{CROSSHEAD}}{1.25 \times 2.44}$$

$$= 16.54 + 0.61 = 17.15 \text{ kN}$$

LL: P_w due to wheel load

For $t = 450 \text{ mm}$


$$F_c = k_1 k_2 k_3 k_4 k_5 k_6 k_7 k_8 k_{12} F_c'$$

(Hard wood from SA \rightarrow F11)

where $\left\{ \begin{array}{l} \rho = 1.22 \\ g_{13} = 1.0 ; l = 6.6 \end{array} \right. \Rightarrow S = \frac{1 \times 6.6}{0.45} = 14.7$

$$\Rightarrow \rho S = 17.9$$

$$k_{12} = 1.5 - 0.05 \rho S = 0.605$$



$$\therefore F_c = 1.7 \times 1 \times 1 \times 1 \times 1 \times 1 \times 0.605 \times 8.4 = 8.64 \text{ MPa}$$

$$F_c = \frac{P_{all}}{A_c} \Rightarrow P_{all} = 8.64 \frac{\text{N}}{\text{mm}^2} \times \pi 225^2 = 1375 \text{ kN}$$

$$= 140 \text{ tonnes/piles}$$

RAPID BAY JETTY	Maunsell	
TIMBER PILE CHECK		
	BY DL	SHEET No. A 26
CHECKED	DATE July '97.	

FOR BENTS 29 - 31, $\phi = 200\text{mm}$

$$S = \frac{1.0 \times 6.6}{0.2} = 33$$

$$PS = 1.22 \times 33 = 40.26$$

$$k_{12} = 200 / (PS)^2 = 0.123$$

$$F_c = 1.7 \times 0.123 \times 8.4 = 1.76 \text{ MPa}$$

$$P_{all} = 1.76 \times \pi 100^2 = 55.3 \text{ kN}$$

$$\therefore P_{all} = DL + LL$$

$$P_{LL} = 55.3 - 17.15 = 38.15 \text{ kN}$$

$$= 3.9 \text{ tonnes}$$

USING FACTOR OF SAFETY OF 1.15

$$\text{ALLOWABLE LOAD} = 3.38 \text{ tonnes}$$

Maunsell

RAPID BAY JETTY

JOB No. 10998


TIMBER PILE CHECK

BY DL

SHEET No. A27

CHECKED

DATE July '97



$$R = 1.8P + 1.8P \times \frac{0.83}{2.43} + \left(P + P \frac{0.83}{2.43} \right) \left(\frac{1.375}{4.875} \right)$$
$$= P (2.793)$$

$$\Rightarrow R = 3.38 \text{ tonnes} = P (2.793)$$

$$P = 1.21 \text{ tonnes}$$


$$\therefore \text{MAX WHEEL LOAD} = 1.8P$$
$$= 2.2 \text{ tonnes/wheel}$$

DRAFT 04/08/97 14:40 PM

Appendix B

Photographs


APPENDIX B
PHOTOGRAPHS




1. View from shore




2. View from shore




3. View from loading head - inner section




4. View from loading head - outer section




5. Motor room 2 and inner end of loader




6. Loader and steel piles at jetty head




7. Tee head and loader




8. Jetty head and loader




9. Crosshead Bent 9




10. Crosshead Bent 12




11. Crosshead Bent 17




12. Crosshead Bent 17




13. Crosshead Bent 19



14. Pile at Bent 27



15. Steel piles at crosshead at Bent 38




16. Steel piles at crosshead at Bent 48




17. Steel pile at Bent 70




18. Stringers between Bents 73 and 74




19. Stringer and bearers between Bents 73 and 74




20. Girder 4 at Bent 73




21. Motor Room No. 3




22. Steel piles and crossheads at Bent 79 and 80




23. Raking steel pile at Bent 76




24. Motor Room No. 3



25. Jetty head platform at Tee head



26. Tee head steel piles peeling off at 1 m above sea level



27. Jetty head and loader




28. Deck at Tee head



29. Deck beyond Bent 81



30. Deck between Motor Room Nos. 2 and 3



31. Motor Room No. 2